



Turning Formulas

Feed Rate:

The rate of insert travel through the workpiece measured in inches per minute.

$$\text{Feed Rate} = \text{Feed} \times \text{RPM}$$

(inches per minute) (inches per revolution)

Cutting Speed:

The velocity of the workpiece as it passes the insert measured in surface feet per minute.

$$\text{Cutting Speed} = \text{Workpiece Diameter} \times .262 \times \text{RPM}$$

(SFM)

Revolutions Per Minute:

The rotating velocity of the machine spindle.

$$\text{RPM} = \frac{\text{Cutting Speed}}{\text{Workpiece Diameter}} \times 3.82$$

(SFM)

Metal Removal Rate:

The speed, measured in cubic inches per minute, that stock is removed from the part being machined.

$$\text{MRR} = \text{Depth of Cut} \times \text{Feed} \times \text{Cutting Speed} \times 12$$

Milling Formulas

Feed Rate:

The rate of insert travel through the workpiece measured in inches per minute.

$$\text{Feed Rate} = \text{Chip load} \times \text{Number of teeth} \times \text{RPM}$$

(inches per minute)

Cutting Speed:

The velocity of the workpiece as it passes the insert measured in surface feet per minute.

$$\text{Cutting Speed} = \frac{\text{Cutter Diameter} \times \text{RPM} \times 3.1416}{12}$$

(SFM)

Revolutions Per Minute:

The rotating velocity of the machine spindle.

$$\text{RPM} = \frac{\text{Cutting Speed} \times 12}{\text{Cutting Diameter} \times 3.1416}$$

Metal Removal Rate:

The speed, measured in cubic inches per minute, that stock is removed from the part being machined.

$$\text{MRR} = \text{Depth of Cut} \times \text{Width of Cut} \times \text{Feed}$$

Chip Load:

Inches Per Tooth

$$\text{Chip Load} = \frac{\text{Feed Rate}}{\text{Number of Teeth} \times \text{RPM}}$$